

## **Care & Maintenance Instructions**

Due to the non-porous surface of the finish, there is no need to use abrasive cleansers. Any household liquid detergent will give excellent results. To remove mineral stains, use a mild acid solution such as a liquid bowl cleaner.

425-205-5712

All organic coatings must cure. They start to cure from the time of application for a total of approximately thirty days.

- 1. Surface will be ready for use in 48 hours
- 2. Do not lay soap, bottles or any objects on the finish for long periods of time (a hanging shower caddy for everyday items is a good idea).
- 3. Leaky faucets must always be repaired.
- 4. Do not use abrasive cleaners. No S.O.S. pads, Comet, or Soft Scrub type products.
- 5. Do not use bath mats with suction cups underneath.
- 6. Any surface dust will dissipate in 3-4 weeks with normal cleaning and usage; do not pick surface dust off with finger.
- 7. The best way to keep the tub clean is to wipe it down with a towel after each use (it's not necessary to wipe it completely dry).
- 8. Caulk around tub before using.
- 9. These are some recommended cleaning products that are safe to use: Lysol Basin & Tile Cleaner, Mr. Clean (liquid), Dow, and Fantastic.

www.AdvancedRefinishing.com